ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0656, W1053, W0654, W1051, W1039, W0636, W0648, W	NA, 2nd Crs, 7th Crs	Near Byatarayanapura sub division office
Segment No.	**Total Length (m)**	
6/C-W0656/S024332	445.64	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	77.88	77.612024	13.053994	77.612705	13.053775	cross road	dead end
2	26.01	77.612730	13.054292	77.612931	13.054164	cross road	dead end
3	53.44	77.612636	13.054731	77.613084	13.054530	cross road	dead end
4	65.40	77.612518	13.054728	77.613046	13.054444	cross road	dead end
5	60.13	77.612284	13.054135	77.612799	13.053934	Dasarahalli band main road	cross road dead end
6	66.00	77.612209	13.054344	77.612577	13.054820	Cross road	Dead end
7	96.78	77.612032	13.054347	77.612850	13.054018	Dasarahalli band main road	cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads, drains and culverts at Dasarahalli Bande and Maruthi layout in ward no. 06 Byatarayanpaura sub division.	6000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	CC road, drains and covering slab
Tender	**Work Details**	**Job No. / Work Code**
Tender	CC road, drains and covering slab	006-18-000002
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/112/2017-18	17/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
17/03/2018	17/03/2019	No

AEE

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh c naik
Date of Inspection	**Remarks**	
03/05/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0656, W1053, W0654, W1051,

AEE

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	05/05/2018	01/06/2018	As proposed
SE	Vasu K M	03/05/2018	01/06/2018	Verified
EE	Mohandas H.T	03/05/2018	01/06/2018	verify
AEE	Sridhar B.S	03/05/2018	01/06/2018	verify
AE	Daramsingh C Naik	03/05/2018	01/06/2018	Mobile verification is done
AE	Daramsingh	02/05/2018	01/06/2018	Forwarded

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0656, W1053, W0654, W1051,